

高雄市立海青高級工商職業學校飲水設備保養記錄表

巡檢保養 更換濾心

日期: 115年 4月 21日

地點	編號	位置	廠牌/型號	電壓	年份	濾心更換日期					機台巡檢	漏電檢測	加熱系統	冷卻系統	TDS	備註
						1	2	3	4	5						
教學大樓	1	1F-1107(教教室內)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	0	17	
	2	1F-1106(學務處內)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	0	14	
	3	1F-1104(總務處後走廊)	樂泉 1000+RO	220/V	102/4		4/20	4/20			0	0	0	0	10	
	4	1F-1101(走廊)	豪星 1688+RO	110/V	111/2		4/20	4/20			0	0	0	/	10	
	5	2F-1209(走廊)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	/	16	
	6	2F-1206(教務處內)	力霸 806A+RO	110/V	108/7		4/20	4/20			0	0	0	0	11	
	7	2F-1205(輔導室後走廊)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	0	20	
	8	2F-1201(走廊)	豪星 1688+RO	110/V	112/2		4/20	4/20			0	0	0	/	8	
	9	3F-1307(走廊)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	0	12	
	10	3F-1306(辦公室)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	0	12	
	11	3F-1301(走廊)	樂泉 1000+RO	110/V	107/5		4/20	4/20			0	0	0	/	15	
	12	4F-1401(走廊)	豪星 1688+RO	110/V	112/2		4/20	4/20			0	0	0	0	13	
	13	5F-1502(辦公室)	樂泉 1000+RO	110/V	100/6		4/20	4/20			0	0	0	/	20	
行政大樓	15	B1-3B11(辦公室房間)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	0	6	
	16	1F-3102(進修主任室)	樂泉 1000+RO	220/V	102/4		4/21	4/21			0	0	0	0	14	
	17	2F-3202(走廊)	豪星 1688+RO	110/V	113/1		4/21	4/21			0	0	0	/	11	
	18	3F-3301(辦公室)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	0	12	
	19	3F-3303(走廊)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	0	3	
	20	4F-3403(走廊)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	/	13	
資訊大樓	14	B1-角力室	豪星 1688+RO	110/V	114/2		4/21	4/21			0	0	0	/	6	
	21	1F-4103(走廊)	豪星 1688+RO	110/V	112/2		4/21	4/21			0	0	0	/	12	
	22	2F-4201(走廊)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	/	11	
	23	2F-4203(辦公室)	樂泉 1000+RO	220/V	102/4		4/21	4/21			0	0	0	0	13	
	24	3F-4304(走廊)	樂泉 1000+RO	110/V	102/4											故障
美工大樓	26	1F-5103(走廊)	樂泉 1000+RO	110/V	105/9		4/21	4/21			0	0	0	0	13	
	27	2F-連接走廊	鑫泉 1000+RO	110/V	105/9		4/21	4/21			0	0	0	/	5	
	28	2F-5205(辦公室)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	0	6	
	29	3F-5301(走廊)	鑫泉 1000+RO	110/V	105/9		4/21	4/21			0	0	0	0	13	
	30	4F-5401(走廊)	鑫泉 1000+RO	110/V	105/9		4/21	4/21			0	0	0	0	14	

鑫泉事業有限公司

電話: 07-373-6758

保養人: 潘弘祐

客戶簽章: 張瑞弘

高雄市立海青高級工商職業學校飲水設備保養記錄表

巡檢保養 更換濾心

日期: 115年 4月 21日

地點	編號	位置	廠牌/型號	電壓	年份	濾心更換日期					機台巡檢	漏電檢測	加熱系統	冷卻系統	TDS	備註
						1	2	3	4	5						
營建大樓	31	1F-6103(走廊)	豪星 1688+RO	110/V	114/2		4/21	4/21			0	0	0	0	12	
	32	2F-6202(辦公室)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	0	11	
	33	2F-6204(辦公室)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	0	13	
	34	3F-6305(走廊)	豪星 1688+RO	110/V	111/2		4/21	4/21			0	0	0	/	12	
	35	4F-6403(走廊)	樂泉 800+RO	110/V	104/11		4/21	4/21			0	0	0	/	14	
電子大樓	36	1F-7103(走廊)	豪星 1688+RO	220/V	112/2		4/21	4/21			0	0	0	/	12	
	37	2F-7201(辦公室)	樂泉 1000+RO	110/V	102/4		4/21	4/21			0	0	0	/	10	
	38	2F-7203(走廊)	豪星 1688+RO	220/V	113/1		4/21	4/21			0	0	0	/	16	
	39	4F-7401(走廊)	樂泉 1000+RO	220/V	102/4		4/21	4/21			0	0	0	0	4	
實習大樓	40	1F-B104(走廊)	豪星 1688+RO	110/V	113/1		4/20	4/20			0	0	0	/	20	
	41	2F-B202(走廊)	豪星 1688+RO	220/V	111/2		4/20	4/20			0	0	0	/	21	
	42	3F-B302(走廊)	樂泉 1000+RO	220/V	102/4		4/20	4/20			0	0	0	0	8	
	43	4F-B403(走廊)	樂泉 1000+RO	220/V	102/4		4/20	4/20			0	0	0	0	5	
活動中心	44	B1-車道旁	豪星 1688+RO	110/V	114/2		4/20	4/20			0	0	0	0	12	
	45	3F-樓梯陽台	豪星 1688+RO	110/V	111/2		4/20	4/20			0	0	0	/	17	
	46	3F-辦公室內陽台	樂泉 1000+RO	220/V	102/4		4/20	4/20			0	0	0	0	4	
室內設計	47	2F-8201(走廊)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	0	12	
	48	3F-8301(走廊)	樂泉 1000+RO	110/V	102/4		4/20	4/20			0	0	0	/	4	
	49	3F-8302(辦公室)	鑫泉 1000+RO	110/V	107/5		4/20	4/20			0	0	0	0	13	
	50	4F-8401(走廊)	豪星 1688+RO	110/V	113/1		4/20	4/20			0	0	0	/	12	
陶瓷室	51	3F-走廊	樂泉 1000+RO	110/V	107/5		4/20	4/20			0	0	0	0	20	
傳達室	52	1F-傳達室內房間	豪星 3187+RO	110/V	98/11		4/21	4/20			0	0	0	/	12	

鑫泉事業有限公司

電話: 07-373-6758

保養人: _____

4/21

客戶簽章: _____

3/8 3/8 3/1

* 濾心代碼

1->PP5U" 濾芯

2->大 T33 活性炭濾心

3->PPIU" 濾芯

4->RO 膜管

5->小 T33 後置活性炭